

# FITNESS CERTIFICATE OF SCHOOL BUILDING

(To be filled by the Inspecting Officer (Assistant Engineer))

1. Name of School : Trinity Lyceum, Nanthirickal, Vellimon P.O
2. Name of Officer : Rajendran.S, Asst. Engineer, LSGD Section  
Perinad Grama Panchayat
3. Location with Educational District/ Sub district : Perinad, Kundara, Kollam
4. Classification of buildings as specified in column : (1) 1 x 55.60 x 8.75 x 3.30m (Three storeyed R.C.C Building)  
for the application for fitness certificate and size : (2) 1 x 40.00 x 8.75 x 3.30m (Three storeyed R.C.C Building)
5. Period for which certificate is issued : 2022-23
6. Nature of Defects if any  
a. Foundation & Basement  
b. Superstructure  
c. Doors & Windows  
d. Wood work wrought & put up  
e. Roof  
f. Flooring  
g. Miscellaneous } : NIL
7. Any major defects noticed which will render the building unsafe in any manner. : No
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound or not for conducting classes : The structure is sound under normal wind and weather conditions.

Certified that the school was inspected by me on 12/06/2022 and found to be fit to conduct classes for the period 2022-23 for the reasons stated above.

Place : Perinad ,

Date : 12/06/2022



Signature:

Designation :

*[Handwritten Signature]*  
ASSISTANT ENGINEER  
Local Self Govt. Dept.  
Perinad Grama Panchayat